

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans Run date 22-Nov-14 Time 9:19 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 355 Const Calendar Day: 823 Date: 05-Sep-2014 Friday
Inspector Name: Liu, Tai-Lin Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 07:00 AM 03:30 PM Break: 00:30 Over Time:

Federal ID: Location:

Reviewer: Awal, Mohammad Approved Date: Status: Submit

Weather

 Temperature
 7 AM
 60 - 70
 12 PM
 70 - 80
 4PM
 70 - 80

 Precipitation
 Condition
 Clear

Working Day 🗸 If no, explain:

Diary:

Tower Activites

CCO # 382 - Tower Painting and Cleaning works (9/5/14, Friday - Clear):

- * Went to job site (T1 by driving to W2) with Grady this afternoon.
- Saw METS paint inspector Justing at the W2 parking lot, he was on the way to tower traver inspecting paint repair.
- There were 6 CCC's painters working in tower from EL. 143 m down to the El. 127m for floor paint repair works. CCC will work in coming weekend for N/W shafts D and E faces paint repair (Tower elevator area).
- * Paint Crew: Sage Ray, Juan Carlos, Luis Ventura, Oscar Salazar, Ramon Gutierrez, Daniel Rosales, Abraham Ventura. Crew worked from 6AM to 2:30 PM, 8 hours shift.
- * Labores: James Sturgeon, Jose Jr. Avila, Victor Hernandez, and Danny Schwartz worked today (8 hours shift) performing hours keeping works.
- Left T1 around 2:20PM,
- * Performed paper work at office, and left office around 4:05 PM.

FLUOR, A J	V						Tower Lift 01 Diaphram Tower SE Erect structural steel (bridge tower)					
	AMERICAN BRIDGE/FLUOR, A JV											
Class	Name	RT Hrs	OT Hrs	DT Hrs	Total	Remarks	Dispute					
RICAN BRIDG	SE/FLUOR, A JV											
JNM	DONALD PLUMB	0.00	0.00	0.00	0.00							
JNM	PAUL FAMBRINI	0.00	0.00	0.00	0.00							
rer JNM	FERMIN MEDINA	0.00	0.00	0.00	0.00							
GEN	AARON KENT	0.00	0.00	0.00	0.00							
rer JNM	LUIS Jimenez	0.00	0.00	0.00	0.00							
rer JNM	DANNY SCHWARTZ	0.00	0.00	0.00	0.00							
rer APP	JAVIER MEDINA	0.00	0.00	0.00	0.00							
rer FOR	GUILLERMO LIMON	0.00	0.00	0.00	0.00							
rer APP	ROGELIO RODRIGUEZ	0.00	0.00	0.00	0.00							
rer JNM	CARLOS MONTEJANO	0.00	0.00	0.00	0.00							
rer APP	JOSE AVILA	0.00	0.00	0.00	0.00							
	RICAN BRIDO JNM JNM orer JNM	RICAN BRIDGE/FLUOR, A JV JNM DONALD PLUMB JNM PAUL FAMBRINI OTER JNM FERMIN MEDINA GEN AARON KENT DOTER JNM LUIS Jimenez DOTER JNM DANNY SCHWARTZ OTER APP JAVIER MEDINA OTER APP ROGELIO RODRIGUEZ OTER JNM CARLOS MONTEJANO	RICAN BRIDGE/FLUOR, A JV	DATE CAN BRIDGE/FLUOR, A JV JNM DONALD PLUMB 0.00 0.00 0.00 JNM PAUL FAMBRINI 0.00 0.	STEELING STEELING	STEP STEP	STEP STEP					

Daily Diary Report by Bid Item

Inspector Name Liu, Tai-Lin Job Name: 04-0120F4 Diary #: 355 Date: 05-Sep-2014 Friday VICTOR HERNANDEZ Semi-Skilled Laborer JNM 0.00 0.00 0.00 0.00 Ironworker FOR JAMES STURGEON 0.00 0.00 0.00 0.00 Rental Company Equipment RT Hrs OT Hrs ST Hrs IT Hrs **Equipment ID** Description Remarks Dispute AMERICAN BRIDGE/FLUOR, A JV Contractor: *E0020562 WELDING EQUIPMENT No 0.00 0.00 0.00 0.00 *E0030562 WELDING EQUIPMENT No 0.00 0.00 0.00 0.00 WELDING EQUIPMENT *E0010562 No 0.00 0.00 0.00 0.00 2292 WELDER, 600 AMP No 0.00 0.00 0.00 0.00 2293 WELDER, 600 AMP No 0.00 0.00 0.00 0.00 Bid Item: 078 04-0120F4 T-L01-ENE.078 **Tower Lift 01 External Paint Tower NE** CERTIFIED COATINGS COMPANY 04-0120F4 Bid Item: 078 T-L05-ENE.078 **Tower Lift 05 External Paint Tower NE** CERTIFIED COATINGS COMPANY 04-0120F4 Bid Item: 078 T-HEA-ENE.078 **Tower Head External Paint Tower NE** CERTIFIED COATINGS COMPANY CCO-355 Bid Item: 001 0-CIC-EFA.355 **CIC - Elevator Impacts - USA Hoist** AMERICAN BRIDGE/FLUOR, A JV

Attachment





Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Liu, Tai-Lin Diary #: 355 Date: 05-Sep-2014 Friday

Tower north elevator side, area still need paint repair



Traver near W2 elevator area



Elevator side of tower



Labor's forman James's truck with unloaded equipment



CCC painters performed paint repair on barrier & piping near tower (North side)



METS paint inspector - Justing went down to traver for inspection - Tower El. 53